

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	350	(219/81).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 15:53
S2	362	(219/83).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 15:54
S3	169	(219/84).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 15:59
S4	429	(219/101). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:00
S5	95	(219/102). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:00
S6	140	(219/103). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:00
S7	510	(219/104). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:01
S8	194	(219/105). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:01
S9	128844	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:12
S10	1	S9 and ((\$1butt \$3 near3 weld \$3) near20 electrode\$1 near20 (convex or curve\$1) near100 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:13

S11	21	S9 and ((((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near20 electrode\$1 near20 (convex or curve\$1) near100 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:14
S12	30	S9 and ((((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near20 electrode\$1 near20 (convex or curve\$1 or round\$2) near100 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:15
S13	63	((((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near20 electrode\$1 near20 (convex or curve\$1 or round\$2) near100 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:33
S14	44	((((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near10 electrode\$1 near10 (convex or curve\$1 or round\$2) near50 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2008/04/24 16:33

S15	18	(((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near10 electrode\$1 near10 (convex or curve\$1 or round\$2) near50 (press \$3 or forc\$3 or deform\$3))	US-PGPUB; USPAT	OR	OFF	2008/04/24 16:38
S16	6	(((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near10 electrode\$1 near10 (convex or curve\$1 or round\$2) near50 (press \$3 or forc\$3 or deform\$3)). clm.	US-PGPUB; USPAT	OR	OFF	2008/04/24 16:38
S17	16	(((\$1butt\$3 or spot or seam or resistance) near5 weld\$3) near10 electrode\$1 near10 (convex or curve\$1 or round\$2)).clm.	US-PGPUB; USPAT	OR	OFF	2008/04/24 16:38

4/ 24/ 08 4:41:25 PM

C:\ Documents and Settings\ kkerens\ My Documents\ EAST\ Workspaces\ 10523579(219) ab.w sp